


SPINDLE REBUILD FOR VOLKMANN 09ST BA3 UPGRADE, 09 THRU 09OS BA4

- A) Bushing
- B) Damping Piece
- C) E13 Inner Race
- D) Thread Guide
- E) Thread Guide Cover
- F) Rivet
- G) Balance Ring
- H) Stainless Steel Twist Plate
- I) Blade & Whorl Assembly
- J) Upper Balance Ring
Yarn Guard, 090 BA4
- K) Torx Screw
- L) Reserve Disc
- M) Hourglass Ceramic
- N) Damping Piece for
Hourglass Ceramic



DESCRIPTION OF BASIC REBUILD SERVICES:		PRICE
EE402021	Upper Spindle Refurbish: Complete Clean-Up, Grind Tip, Replace E13 Race (C), Balance Ring (G), Damping Piece (N), New Hardware, and Balance	CALL FOR PRICING
	If Stainless Twist Plate EE440190 (H) is required, then TOTAL PRICE is...	
	If Blade & Whorl EE440376 (I) and Twist Plate (H) are required for 09ST BA3 Upgrade, then TOTAL PRICE is...	
	If Blade & Whorl EE440388 (I) and Twist Plate (H) are required for 09O/09OS BA4, then TOTAL PRICE is...	

EE402171	Rebuild & Resleeve 09ST Upgrade BA3 and 09O/09OS BA4	CALL FOR PRICING
----------	--	------------------

ADDITIONAL ITEMS:		PRICE
EE480972	Replace Reserve Disc (L)	CALL FOR PRICING
EE402099	New Bolster Only	
EE440051	Lower Spindle Complete, Bolster with Brake Shoe, Pin and Washers	
EE480195	New Brake Shoe Only	

Revised: August 13, 2008

