

Tube Disc Assembly Complete, 72.5mm


for Superba Winder, B400, B401, BLA




**IMPROVED
DESIGN**

THE TORQUE / MOMENT FORCE ON THE BEARING IS DECREASED ON THE NEW DESIGN, SINCE THE BEARING IS NOW LOCATED DIRECTLY UNDERNEATH THE LOAD OF THE PACKAGE

RECESS PROVIDES BETTER RETENTION OF THE TUBES WITH WORN ENDS.





OLD DESIGN:



THE OLD DESIGN ALLOWS A HIGH TORQUE / MOMENT FORCE TO BE EXERTED ON THE BEARING, SINCE THE BEARING IS LOCATED A GREATER DISTANCE AWAY FROM THE LOAD OF THE PACKAGE

EE130015

Tube Disc Assembly Complete, 72.5mm for Superba Winder,
 Improved Design
 OEM: (730-142-523)



P O Box 979
 Southern Pines NC 28388-0979
 845 Valley View Road
 Southern Pines NC 28387

Phone: 910-692-5441 or
 Toll Free: 800-648-7273
 Fax: 910-692-4147 or
 Toll Free: 888-692-4147

Email: epic@epicenterprises.com
 Website: www.epicenterprises.com

**Parts and Services
 you can rely on!**

Epic products are intended as replacements for worn or damaged parts in OEM products. OEM Part numbers in (parenthesis) indicate either 1) improved design 2) the part serves the same function as the OEM part, but may differ from the OEM design, 3) it is a component of an assembly where no OEM reference number is available, or 4) it is a repair service for the referenced part.

Parts with EE designations are manufactured by Epic and are not authorized by the original equipment manufacturers., ©Epic Enterprises, Inc., October 2014

EE is an Epic trademark designating Epic parts

Superba is a trademark of Superba SAS