

New Product Information





For Volkmann 05/05C/05O/05OC/05OCF BA5.01, BA5.02, BA5.03, BA8.01, BA8.02



New Pots with Flat Seam Design

EE440426- Shell, New, without Slots, 05C/05OC/05OCF, BA5.01, BA5.02, BA5.03, BA8, Stainless Steel (302mm) OEM: (500603), (500629), (690222)

EE440427- Shell, New, with Slots, 05/05C/05O/05OC, BA5.01, BA5.02, BA5.03, BA8, Stainless Steel (302mm) OEM: 467316, 493544, 500611, 690214

EE440479- Shell, New, without Slots, 05/05C/05O/O5OC, BA8.01, BA8.02, Stainless Steel (275mm)

OEM: 689836

Pot Repair

EE440415 - Customer's, without Slots, Repaired: Volkmann

05C/05OC/05OCF, BA5.01, BA5.02, BA5.03, BA8,

Stainless Steel (302mm)

OEM: (500603), (500629), (690222)

EE440480- Customer's, without Slots, Repaired: Volkmann 05/05C/05O/O5OC, BA8.01, BA8.02, Stainless Steel (275mm)

OEM: (689836), (1058866)

EE440482 – Customer's, with Slots, Repaired: Volkmann 05/05C/05O/05OC, BA5.01, BA5.02, BA5.03, BA8,

Stainless Steel (302mm)

OEM: (467316), (493544), (500611), (690214)



P O Box 979 Southern Pines NC 28388-0979 845 Valley View Road Southern Pines NC 28387

Phone: 910-692-5441 or Toll Free: 800-648-7273 Fax: 910-692-4147 or Toll Free: 888-692-4147

Email: epic@epicenterprises.com Website: www.epicenterprises.com

Parts and Services you can rely on!

Epic products are intended as replacements for worn or damaged parts in OEM products. OEM Part numbers in (parenthesis) indicate either 1) improved design 2) the part serves the same function as the OEM part, but may differ from the OEM design, 3) it is a component of an assembly where no OEM reference number is available, or 4) it is a repair service for the referenced part.

Parts with EE designations are manufactured by Epic and are not authorized by the original equipment manufacturers., @Epic Enterprises, Inc., July 2015